

HDPE Cleaning & Maintenance

Clean HDPE products by scrubbing with soap and water solution using a soft sponge or plastic bristled brush. Use a soft bristled toothbrush to clean spaces that are hard to reach.

If deep cleaning with a pressure washer, use the lightest setting. It is not recommended to use more than 1,500psi. Keep the tip of the pressure washer at least 10-12-inches away from the material so it does not get damaged.